

US EPA ARCHIVE DOCUMENT

LANDFILL SITE ASSESSMENT

Facility Name :	Magnolia Landfill	Facility Location ID :	110010380346
Assessment Date :	8/27/2010	Incident Name :	BP Spill
Physical Location :	15140 County Road 49		
City, State :	Summerdale , AL	County :	Baldwin

ASSESSMENT INFORMATION

General Site Information and Observations	
1. Is the facility currently receiving debris from BP?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. If no, has the facility received debris from BP in the past?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
3. Which companies are transporting the BP waste?	Waste Management; Republic-Allied
4. How many BP waste loads have been rejected?	None
5. If so, why?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
Additional Comments : During this operational period Ken Feely, Waste Disposal Technical Specialist, conducted a site monitoring visit from 1345 hours to 1430 hours at the Baldwin County (Magnolia) landfill. Stephanie Hopper (ADEM) and Ed Fox (Baldwin County) were present during the visit.	